



Sauter GmbH

Ziegelei 1
D-72336 Balingen
e-mail: info@kern-sohn.com

Phone : +49-[0]7433- 9933-0
Fax: +49-[0]7433-9933-149
Internet: www.sauter.eu

Instruction Manual Ultrasonic Material Thickness Gauge

SAUTER TN-US

Version 2.0
04/2020
GB



PROFESSIONAL MEASURING

TN_US-BA-e-2020



SAUTER TN-US

V. 2.0 04/2020

Instruction Manual Ultrasonic Material Thickness Gauge

Congratulations on the purchase of an ultrasonic material thickness gauge from SAUTER. We hope you will enjoy your quality measuring device with its wide range of functions.

For questions, wishes or suggestions we are at your disposal.

Table of contents:

1.	General overview	4
1.1	Technical data.....	4
1.2	General functions	5
1.3	Measuring principle.....	5
1.4	Equipment	6
2.	Design features	7
2.1	Digital display	7
2.2	Description of the control panel	8
3.	Preparation for commissioning	8
3.1	Selection of the sound generator	8
3.2	Conditions and preparations for surfaces	10
4.	Mode of operation.....	11
4.1	Switching on and off	11
4.2	Sound generator setting (zero setting)	11
4.3	Sound velocity	11
4.4	Measurements are made	13
4.5	The ultrasound image mode (scan mode)	14
4.6	Change the resolution.....	14
4.7	Changing the units	15
4.8	Storage management	15
4.9	"Beep" mode.....	16
4.10	EL Backlight.....	16
4.11	Battery information	16
4.12	Automatic switch-off.....	16
4.13	Basic setting of the system (Reset).....	16
4.14	Connection to PC	16
5.	Maintenance	17
6.	Transport and storage.....	17
7.	Sound velocities	17
8.	The measurement of tubes and hose material	18
9.	Measuring hot surfaces.....	18

10.	Measuring coated materials.....	18
11.	Material suitability.....	19
12.	Coupling means	19

1. General overview

The TN-US is a digital ultrasonic material thickness gauge. It is based on the same operating principle as the SONAR. The TN-US can measure the thickness of a wide range of materials with a measuring accuracy of up to 0.1 mm or 0.01 mm. It can be used for a wide range of hard and homogeneous materials..

1.1 Technical data

	TN 80- 0.01US	TN 80- 0.1US	TN 230- 0.01US	TN 230- 0.1US	TN 300- 0.01US	TN 300- 0.1US
Dispaly	4.5 inch LCD display with backlight					
Measuring range	0.75~80mm		1,2~230mm		3~300mm	
Sound speed	1000~9999m/s					
Resolution	0.01mm	0.1mm	0.01mm	0.1mm	0.01mm	0.1mm
Measurement uncertainty	±0.5% +0.04mm					
Memory	of up to 20 files (up to 99 measured values per file) with stored measured values					
Power supply	2x 1,5V AA batteries					
Communicati on	USB	NA	USB	NA	USB	NA
Ambient temperature	-20°C - 60°C					
max. air humidity	≤ 90%					
Dimensions	150x74x32mm					
Weight	245g					

1.2 General functions

A wide range of materials can be measured, including metals, plastics, ceramics, composites, epoxy, glass and other ultrasonic wave conductive materials.

For special applications, certain models of sounders are available, especially for coarse-grained materials and high-temperature applications.

- Zero setting and sound velocity calibration function.
- Two-point calibration function
- two working methods: single point mode and ultrasound image mode (scan mode)
- Coupling status display shows the coupling status.
- The battery information shows the remaining capacity of the battery.
- "Auto Sleep" and "Auto Power off" function to conserve battery power.
- Software for TN xx0.01 US available on request to transfer memory data via USB connection to the PC

1.3 Measuring principle

The Ultrasonic Digital Material Thickness Gauge measures the thickness of a part or structure by accurately measuring the time taken for a short ultrasonic pulse to pass through the thickness of a material, controlled by a transducer, then reflected from the back or inner surface and returned to the transducer.

This measured two-way transmission time is divided by 2 (representing the outward and return paths), and then multiplied by the sound velocity of the corresponding material. The result is calculated with the following formula:

$$H = \frac{v \times t}{2}$$

H = Material thickness of the test object


v = sound velocity of the corresponding material

t = the measured transit time for the sound

1.4 Equipment


	No.	Designation	Quantity	Note
Standard Equipment	1	Main body	1	
	2	Ultrasonic probe	1	depending on model
	3	Coupling means	1	
	4	Transport case	1	
	5	Operating instructions	1	
	6	Alkaline battery	2	Gr. AA
Optional accessories / Re-adjustment	7	Ultrasonic probe ATU-US 01	1	
	8	Ultrasonic probe ATU-US 02	1	
	9	Ultrasonic probe ATB-US 02	1	
	10	Ultrasonic probe ATU-US 10 right angle	1	
	11	Ultrasonic probe ATU-US09	1	
	12	Ultrasonic probe ATB-US01	1	
	13	Data Pro Software ATU-04	1	for PC only with models TN xx 0.01 US
	14	Plug-In Software AFI-1.0	1	
	15	USB comm. cable FL-A01	1	
	16	Ultrasonic contact gel ATB-US03	1	

2. Design features



- 1 The main unit (display unit)
- 2 Keypad
- 3 LCD display
- 4 Pulse encoder socket
- 5 Radiation receiver socket
- 6 Zero plate
- 7 PC connection socket
- 8 Label (on the back)
- 9 Battery cover
- 10 Ultrasonic probe

2.1 Digital display



1. Pairing status: shows the pairing status; This symbol must appear while measurements are being taken. If this is not the case, the instrument has problems obtaining stable measurements and it is very likely that deviations will occur.
2. Unit: mm or inches for the material thickness m/s or in/μ s for the speed of sound
3. Battery indicator: shows the remaining capacity of the batteries
4. Information on the display: The determined material thickness value and the speed of sound can be read off and indicates the current operation.

2.2 Description of the control panel

	Switching on/off		Calibration Sound velocity
	Background lighting On/ Off		Enter key
	Button f. Reset		Plus; US mode On/ Off
	Button to change the Units		Minus; Beep mode On/ Off
	Save data or delete		

3. Preparation for commissioning

3.1 Selection of the sound generator

With this instrument a wide range of materials can be measured, from various metals to glass and plastic. For these different types of materials, different sounders, i.e. US measuring heads, are required. The correct transducer is crucial for a reliable measurement result. The following sections explain the important characteristics of the transducers and what should be considered when selecting a transducer for a specific work object. Generally speaking, the best transducer for a workobject should send sufficient ultrasonic energy into the material to be measured so that a strong, stable echo arrives at the instrument. Certain factors influence the strength of the ultrasound as it is transmitted.

These can be read in the following:

The initial signal strength: The stronger a signal is from the beginning, the stronger the returning echo will be. The initial signal strength is mainly a factor of the size of the ultrasonic emitter in the transducer. A strong emitting surface will emit more energy into the material than a weak one. Consequently, a so-called "1/2 inch" US probe will emit a stronger signal than a "1/4 inch" US probe.

Absorption and scattering: When the ultrasound passes through any material, it is partially absorbed. In materials with a granular structure, the sound waves scatter. Both of these influences reduce the strength of the sound waves and thus the ability of the device to detect or record the returning echo. Sound waves with higher frequencies are more "swallowed" than those with lower frequencies.

So it might seem, it would be better to use a low frequency probe in any case, but these are less alignable (bundled) than those with high frequencies. Consequently, a high-frequency transducer would be the better choice for detecting small depressions or impurities in the material.

Geometry of the transducer: The physical limits of the measurement environment sometimes determine the suitability of the transducer for a particular test object. Some sounders are simply too large to be used in a fixed environment. If the available surface for contact with the

sound generator is limited, a sound generator with a small contact area is required.

If a curved surface is measured, e.g. a drive cylinder wall, the contact surface of the sound generator must also be adapted to it.

Temperature of the material: If measurements are made on unusually hot surfaces, high-temperature sounders are used. These are built in such a way that they can be used at high temperatures for special materials and techniques without suffering damage. In addition, care must be taken when performing a "zero calibration" or "calibration with known material thickness" using a high temperature transducer.

The selection of a suitable sound generator is often a compromise between different influences and characteristics. Sometimes it is necessary to select several to try out sounders until the most suitable one for the test object is found.

The sound generator is the "end piece " of the measuring instrument.

It transmits and receives ultrasonic waves, which the device uses to measure the thickness of the material to be examined. The transducer is connected to the gauge by an adapter cable and two coaxial connectors. When sounders are used, plugging in the connectors is simple: either the plug fits into the socket or into the instrument itself. The transducer must be used correctly to obtain accurate, reliable measurement results.

The following is a brief description of one of these, followed by instructions for use.



The upper figure shows the bottom view of a typical sound generator. The two half circles are visible, visibly divided in the middle. One of the semicircles directs the ultrasound into the material to be measured and the other directs the echo back to the transducer. When the transducer is placed on the material to be measured, it is located directly below the center of the area whose thickness is to be measured.

The picture below shows the top view of a sound generator.

It is pressed with the thumb or index finger from above on the sound generator to keep it exactly placed. Only moderate pressure is required, as its surface only needs to be positioned flat on the material to be measured.

Model	Freq MHZ	Ø mm	Measuring range	Lower limit	Description
ATU- US 01	2,5	14	3.0mm~300.0mm (Stahl) 40mm (grey cast iron HT200)	20mm	For thick, highly damping or highly scattering materials
ATU- US 09	5	10	1.2mm~230.0mm (steel)	Φ20mm×3.0mm	Normal measurement
ATU- US 10	5	10	1.2mm~230.0mm (Stahl)	Φ20mm×3.0mm	Normal measurement, 90°angle
ATU- US 02	7	6	0.75mm~80.0mm (Stahl)	Φ15mm×2.0mm	For thin or slightly bent tube material
ATB-US01	5	6	0.75mm~80.0mm (in steel)	Φ15mm×2.0mm	Thin material
ATB- US 02	5	12	3~200mm (steel)	30mm	For high temperature measurements (up to 300°C)

3.2 Conditions and preparations for surfaces

For any kind of ultrasonic measurement, the condition and roughness of the surface to be measured is of utmost importance. Rough, uneven surfaces can restrict the penetration of the ultrasonic waves through the material, resulting in unstable, incorrect measurement results

The surface to be measured should be clean and free of any substances, rust or verdigris. If this is the case, the sound generator cannot be cleaned can be placed on the surface. A wire brush or scraper is often helpful to clean the surface. In extreme cases, belt sanders or the like can be used. However, it is important to avoid gouging the surface, which prevents the sound generator from being placed cleanly.

Extremely rough surfaces like siliceous cast iron are very difficult to measure. These types of surfaces behave like when light shines on frosted glass, the beam is scattered and sent in all directions.

In addition, rough surfaces contribute to considerable wear of the sounders, especially in situations where they are "scrubbed" over the surface.

They should therefore be checked at a certain distance, especially at the first signs of unevenness on the contact surface. If it is worn down more on one side than the other, the sound waves can no longer penetrate vertically through the material surface of the test object. In this case, small irregularities in the material are difficult to measure because the sound beam is no longer exactly below the sound source.

4. Mode of operation

4.1 Switching on and off

The device is switched on and off by the on/off button.

In the device there is a special memory in which all measurements are stored, even after switching off.

4.2 Sound generator setting (zero setting)

The key  is used to zero the device. This is done almost like with a mechanical precision measuring instrument (micrometer).

If this is not done correctly, all measurements performed may be incorrect.

When the instrument is zeroed, the specified error value is measured and automatically corrected for all subsequent measurements.

The procedure is as follows:

1. The sound generator (the ultrasonic probe) is plugged in and the connections of the plugs are checked. The contact surface of the sound generator must be clean.
2. Press the key to  activate the zero setting mode.
3. The key  and the key  are pressed to display the currently used sound generator model. Of course, no mistake should be made here, as this is crucial for the measuring accuracy.
4. A drop of coupling agent is now applied to the metal zero plate.
5. The ultrasonic probe is carefully pressed onto the zero plate and should lie flat on this surface. Now the value 4mm appears because the zero plate is 4mm thick and the instrument is now calibrated to this value.
6. Now the ultrasonic probe is lifted off the zero plate.

The instrument has now recognized the initial error factor and will use it to adjust all subsequent measurements. When zeroing, the instrument will always use the sound velocity of the built-in zero plate, even if other values have been previously entered to make current measurements.

Although the last zero setting is saved, it is recommended to do it again each time the unit is switched on, even if a different sound generator is used. This will ensure that the unit is always set correctly. Pressing the  button cancels the current zero setting. The instrument returns to the measuring mode.

4.3 Sound velocity

In order to be able to make exact measurements, this must be adjusted to the speed of sound of the corresponding material. Different materials have different sound velocities.

If this is not done, all measurements will be faulty by a certain percentage.

One-point calibration is the most common way to optimize linearity over a long range.

Two-point calibration allows higher accuracy at a shorter range by calculating the zero setting and the speed of sound.

Note: For **one-point and two-point calibrations**, paint or coating must be removed in advance. If this is not done, the calibration result will consist of a kind of "multi-material sound velocity" and will certainly not be the same as that of the actual material to be measured.

4.3.1 Calibration with known material thickness

Note: This procedure requires a sample of the material to be measured, the exact material thickness of which, e.g. on any species was measured before.

1. The zero setting is made.
2. The sample material is provided with coupling gel.
3. The ultrasonic probe is pressed onto the piece of material. A material thickness value is now read on the display and the coupling symbol appears.
4. As soon as a stable reading value is reached, the ultrasonic probe is lifted off again. If the thickness of the material just detected changes from the value that existed during coupling, step 3. must be repeated.
5. The key  is pressed and thus the calibration mode is activated. The MM (or IN) symbol should start flashing.
6. With the and  keys you  can now adjust the required material thickness (that of the material pattern).
7. The key  is pressed again and the M/S (or IN/ μ S) should start flashing. The display will now show the sound velocity value previously calculated based on the material thickness.
8. To exit the calibration mode, press the  key to return to the measuring mode. From now on measurements can be made.

4.3.2 Calibration at known sound velocity

Note: For this procedure the sound velocity of the material to be measured must be known. A table of the most common materials can be found in Appendix A of this manual.

1. Press the key to activate  the calibration mode. The MM (or IN) symbol should start flashing.
2. Press this button repeatedly so that the M/S (or IN/ μ S) symbol also flashes.
3. Use the and  keys to  adjust the sound velocity value up or down until it corresponds to the sound velocity of the material to be measured. It is also possible to use the key to  switch between the preset, generally used velocities of sound.
4. To exit the calibration mode,  press the key. From now on measurements can be made.

In order to obtain the most accurate measurement result possible, it is generally recommended to calibrate the measuring instrument with a material sample of known material thickness.

The material composition itself (and thus the speed of sound) often varies from one manufacturer to another. Calibration with a material sample of known thickness ensures that the instrument is adjusted as accurately as possible to the material to be measured.

4.3.3 Two-point calibration

This procedure assumes that the user has two known material thickness points of the test material and that these are representative for the measuring range.

1. The zero setting is made
2. Coupling agent is applied to the material sample.
3. The US measuring probe is placed on it (at the first or second calibration point) and the correct position of the US measuring head on the material sample is checked. The display should now show a measured value and the coupling symbol should appear.
4. As soon as a stable measured value is reached, the sound generator is lifted off. If the reading differs from that when the transducer was coupled, step 3 must be repeated.
5. The key  is pressed and the M/S (or IN/ μ S) should start flashing.
6. The and  keys  can now be used to correct the required material thickness on the display until it matches that of the material pattern.
7. The key  is pressed and the display shows 10F2. The steps 3. to 6. are now repeated for the second calibration point.
8. The  key is pressed so that the M/S (or IN/ μ S) starts to flash. The instrument now displays the sound velocity value that it has calculated based on the material thickness value entered in step 6.
9. Press the key  again to exit the calibration mode. You can now start measuring in the preprogrammed measuring range.

4.4 Measurements are made

The meter always stores the last measured value until a new value is added.

For the sound generator to function properly, there must be no air bridges between its contact surface and the surface of the material to be measured. This is achieved with the ultrasonic gel, the "coupling agent". This liquid "couples" or transmits the ultrasonic waves from the transducer into the material and back again. Before the measurement, a little coupling agent should therefore be applied to the material surface to be measured. Even a single drop is sufficient.

Then the US measuring probe is carefully pressed firmly onto the material surface. The coupling symbol and a number appears in the display. If the instrument is "cleanly adjusted" and the correct sound velocity has been determined, the number in the display shows the current material thickness, measured directly under the sound generator.

If the coupling indicator does not appear or the number on the display is questionable, first check that there is sufficient coupling agent at the point under the US probe and

that it has been placed flat on the material. Sometimes it is necessary to try a different transducer for the material in question (diameter or frequency).

While the US measuring probe is in contact with the material to be measured, four measurements are taken per second. When it is lifted from the surface, the display shows the last measurement.

Note: Sometimes a thin film of the coupling agent is drawn between the US probe and the material surface when the probe is lifted off. In this case it is possible that a measurement is made through this film, which then turns out to be larger or smaller than it should be. This is obvious because if one measurement is taken while the US probe is still in place and the other when it has just been lifted off. In addition, when materials with thick paint or coating are used, they are measured instead rather than the intended material. Ultimately, the responsibility for the clean use of the gauge in connection with detecting these phenomena is withheld from the user.

4.4.1 Changing the individual sound velocities

Annex A lists the individual sound velocities used for the measurement of different materials.

If the speed of sound is to be changed, proceed as follows:

1. The CAL button is pressed twice until the M/S symbol starts to flash.
2. Then press the SCAN or ALARM button to change the speed of sound.
3. Now press the Cal- button to save the changes.

4.5 The ultrasound image mode (scan mode)

While the instrument excels in single point measurements, it is sometimes desirable to examine a larger area to look for the thinnest point. This instrument has a scan mode feature that allows you to do just that.

In normal operation, four measurements are taken per second, which is very appropriate for single measurements. In scan mode this is ten measurements per second and the readings are shown on the display. While the transducer is in contact with the material to be measured, the instrument automatically searches for the smallest reading. The transducer can be "scrubbed" over the surface, because short interruptions of the signal are ignored. In the case of interruptions lasting longer than two seconds, the smallest measured value found is displayed. If the transducer is lifted, the smallest measured value found is also displayed.

When the scan mode is switched off, the single point measuring mode is automatically switched on.

The scan mode can be switched off as follows:

The key  is pressed to switch it on or off. The current state of the scan mode appears on the screen.

4.6 Change the resolution

The device TN xx0.01 US has two selectable screen resolutions, 0.1mm and 0.01mm.

This option is not available for the TN xx0.1 US device. It is limited here to 0.1mm. If the key is pressed  after switching on, the resolution can be selected between "high" (high) and "low" (low).

4.7 Changing the units

Starting from the measuring mode, the unit can be changed by pressing  the key and selecting between mm (metric) and inch (English).

4.8 Storage management

4.8.1 Saving a meter reading

The measured values can be stored in the device with 20 files (F00-F19). For each file there are at least 100 registers (material thickness values) that can be stored. If the key  is pressed after a new reading is displayed, the measured material thickness is stored in the current, running file. If you want to change the file in which the measured values are stored, proceed as follows:

1. Press the key to  activate the data collection function and to read the current file name and the total number of all data records in the file.
2. Use the and  keys to  set the desired file as the current one.
3.  This program can be exited at any time with the key.

4.8.2 Delete the contents of a specific file

It is also possible to completely delete the contents of a file, which allows the user to create a new list of measurements in memory location L00. The procedure is as follows:

1. Press the key to  activate the data collection function and to read the current file name and the total number of all data records in the file.
2. With the and  key you  can scroll back and forth in the file until the corresponding file is found.
3. At the desired file, press  the button and the contents will be deleted automatically. The display shows the "-DEL" symbol.
4.  This program can be exited at any time with the key and the measuring mode can be returned to.

4.8.3 Entering/deleting stored data records

This function allows the user to enter or delete a data record in a desired, previously saved file.

The following steps have to be taken:

1. Press the key to  activate the data collection function and to read the current file name and the total number of all data records in the file.
2. Use the and  keys to  highlight the desired file.
3. Press the key to  open the desired file and the display shows the current data set (e.g. L012) and its contents.
4. Use the and  keys to  select the desired data record.

5. Press the key  at the desired position. It is now automatically deleted and the display shows "-DEL".
6.  This program can be exited at any time with the key and the measuring mode can be returned to.

4.9 "Beep" mode

If the "Beep" mode is activated under ((On)), a short "honk" can be heard each time the key is pressed, each time a measurement is taken and if the measured value exceeds the tolerance limit.

This option can be switched on and off  with the key and the symbol is visible on the display.

4.10 EL Backlight

This allows it to be used in a dark environment. The button is used to  activate and deactivate the background light as soon as the meter is turned on.

As the EL light consumes a lot of electricity, it should only be switched on when needed.

4.11 Battery information

Two AA alkaline batteries are required as energy source. After several hours of use, the display will show the symbol . The larger the black portion in the symbol, the fuller the battery is. When the battery capacity is exhausted, the following symbol appears  and starts flashing. The batteries should now be replaced.

When changing the polarity must be observed.

If the device is not used for a longer period of time, the batteries should be removed.

4.12 Automatic switch-off

The device has an automatic switch-off function to save the batteries. If no button is pressed for more than 5 seconds, the unit switches off automatically.

It also switches off when there is insufficient battery voltage and the battery is almost exhausted.

4.13 Basic setting of the system (Reset)

The key  is pressed during power-up to restore the factory settings. All memory data is also deleted. This procedure can be helpful if the parameter in the meter has become unusable.

4.14 Connection to PC

The device TN xx0.01 US is equipped with the standard USB adapter connection. With the optionally available cable the connection to a PC or external storage devices is possible. The measurement data stored in the instrument memory can be transferred via this cable through the USB access.

For detailed information on the communication software, please read the software manual.

5. Maintenance

If you experience any unusual problems with your US thickness gauge, please do not repair, replace or disassemble it at your own risk. The enclosed warranty card should be filled out and the gauge returned to us. The maintenance will then be carried out by us.

6. Transport and storage

1. The meter should not be exposed to vibrations, strong magnetic fields, decomposing media or dust, and should not be handled roughly. It should be kept at normal temperature.


7. Sound velocities

Material	Sound velocity	
	In/us	m/s
Aluminium	0.250	6340-6400
Conventional steel	0.233	5920
Stainless steel	0.226	5740
Brass	0.173	4399
Copper	0.186	4720
Iron	0.233	5930
Cast Iron	0.173-0.229	4400 – 5820
Lead	0.094	2400
Nylon	0.105	2680
Silver	0.142	3607
Gold	0.128	3251
Zinc	0.164	4170
Titanium	0.236	5990
Sheet metal	0.117	2960
Epoxy	0.109	2760
Resin	0.100	2540
Ice	0.157	3988
Nickel	0.222	5639
Plexiglas	0.106	2692
Styrofoam	0.092	2337
Porcelain	0.230	5842
PVC	0.094	2388
Quartz glass	0.222	5639
Rubber	0.091	2311
Teflon	0.056	1422
Water	0.058	1473

8. The measurement of tubes and hose material

If a piece of pipe is measured to determine the thickness of the pipe wall, the positioning of the transducer is important. If the diameter of the pipe is greater than 4 inches, the position of the transducer on the pipe should be such that the incision on the contact surface is perpendicular to the long axis of the pipe.

For smaller pipe diameters, two measurements should be made at the same location, one with the incision on the contact surface perpendicular to the long axis and the other parallel to it. The smaller of these two measurements is then taken as the exact measurement of this point.



9. Measuring hot surfaces

The velocity of sound through a given material depends on its temperature. With increasing temperature, the speed of sound decreases. For most applications with a surface temperature of less than 100°C no further precautions need to be taken. At temperatures above this, the change in the speed of sound through the material to be measured begins to have a noticeable effect on the ultrasonic measurement.

At such high temperatures, it is recommended to first calibrate with a material sample of known material thickness, which corresponds exactly or approximately to the temperature of the material to be measured. This allows the instrument to calculate the exact sound velocity through the hot material.

For measurements on hot surfaces it may also be necessary to use a "high temperature sound generator". These are specially designed for use at high temperatures, especially since contact with the material surface should be maintained for a short period of time for stable measurement.

While the sound generator is in direct contact with the hot surface, it heats up. Thermal expansion and other effects can have a negative impact on the measuring accuracy.

10. Measuring coated materials

Coated materials are special because their density (and therefore the speed of sound) can vary considerably from one piece to another.

Even through a single surface, noticeable differences in the speed of sound can be detected. The only way to obtain an accurate measurement result is to first perform a calibration on a material sample of known thickness. Ideally, this should be from the same piece as the material to be measured, at least from the same production series. With the help of the "pre-calibration" the deviations are reduced to a minimum.

An additional important factor when measuring coated materials is that any trapped air gap causes premature reflection of the ultrasonic beam. This is noticeable in a sudden

decrease of the material thickness. While on the one hand this prevents the exact measurement of the total material thickness, on the other hand the user is positively alerted to air gaps in the coating.

11. Material suitability

Ultrasonic material thickness measurements are based on the fact that a sound is sent through the material to be measured. Not all materials are suitable for this. Ultrasonic measurement can be applied practically to a wide range of materials including metals, plastics and glass. Difficult materials include some cast materials, concrete, wood, fiberglass and some rubber.

12. Coupling means

All ultrasonic applications require a medium to transmit the sound from the transducer to the test material. Typically this is a very viscous medium.

The ultrasound cannot be efficiently transmitted through air.

A variety of coupling means is used. For most applications propylene glycol is to be used. Glycerine is recommended for difficult applications, as maximum sound transmission strength is required. However, glycerine can cause corrosion due to water absorption in some metals.

Other coupling agents for measurements at normal temperatures may include water, various oils or greases, gels and silicone fluids. High temperature measurements require special high temperature coupling agents.

A characteristic of ultrasonic measurement is that the instrument uses the second rather than the first echo from the rear surface of the material to be measured when in standard pulse-echo mode. This results in a reading that is **twice** as large as it should be.

The responsibility for the appropriate use of the measuring instrument and the detection of these phenomena lies exclusively with the user himself.

Note:

To view the CE declaration, please click on the following link:

<https://www.kern-sohn.com/shop/de/DOWNLOADS/>