





	A	B	C	D	E	F	G	H	I	J	K
1	S	V	Units	DeviceName	UpstartTime	EventTime	DateTimeMeasurement	TimeMeasurement			
2	4.119089991	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
3	4.218979508	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
4	4.318859348	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
5	4.418979688	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
6	4.518997913	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
7	4.6189932	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
8	4.756788039	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
9	4.850050448	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
10	4.978950968	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
11	5.09149461	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
12	5.189141311	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
13	5.318968753	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
14	5.418994899	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
15	5.518911742	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
16	5.618993577	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
17	5.71891123	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
18	5.818979932	0 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
19	5.918927722	-0.1 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
20	6.018913794	-0.4 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
21	6.178278699	-0.7 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
22	6.298945051	-1.1 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
23	6.399081553	-2.1 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
24	6.499050427	-3.1 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
25	6.618930754	-4.1 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
26	6.713073277	-5.1 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
27	6.818910932	-7.5 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
28	6.918912103	-8.7 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
29	7.018993475	-10 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
30	7.118993188	-10.9 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			
31	7.218912121	-12.1 s	N	FH 200	NAN	NAN	2011-11-09T11:51:26.0917552+01:00	0.1			



Data transfer software for force-time-measurements

Features

- Force measurements can be conducted over a very short period, i.e. seconds
- A high speed data transfer to a PC is possible (with a transfer of up to 20 data sets per second) when combining the AFH FAST with SAUTER FH, FC or FL
- AFH FAST shows the results in a Force-Time-Graph and can export the data to Microsoft Excel®
- Compatible with the following operating system: Microsoft Windows 10®

Technical data

- Data recording rate approx. 20 measurements per second with SAUTER FH, FC, FL, DA and DB

Accessories

- **1** RS-232/USB adapter, to connect peripheral devices with USB connection, SAUTER AFH 12
- RS-232/Ethernet adapter for connection to an IP-based Ethernet network, KERN YKI-01

STANDARD

