Instruction manual: Digital Timer (MX6061)

Setting up power supply

Base station

1. Remove the battery compartment cover.

2. Insert the 1 x AAA battery into the battery compartment. Ensure that the battery polarity is correct.

3. Close the battery compartment cover.

Main features

1. The max minute and second number is 99:59.

2. Time Counting down and counting up function.

3. Buttons: M(minutes),S(seconds), Clean, ST(start), SP(stop)

Get started

1. The LCD displays 00:00 after powered on.

2. Press ST button to start counting up time directly / Press M button to set the desired minutes, press S button to set the desired seconds.

3. Press ST/SP button to start counting down.

4. Press ST/SP button to stop counting down. / When the time is up, you will hear a loud beep.

5. Press Clean button to clean the display.

6. Press both M and S button for resetting it.

The timer can be attached to a metal surface with magnetic back, or it can be placed on a flat surface.

Product dimension: 70x 65x20 mm

Product weight: 51 g

Operating Temp: 0 °C to 50 °C

Operating Humidity: 20% to 95% RH