


Please update to windows 10 driver by following steps.

Please extract the attached zip file, and follow the steps below to install the driver.


If you cannot get the attached zip file correctly, you can download from the following link.

<https://drive.google.com/open?id=1fidlWKxmZYauoECKifYxdiljWlagkU9u>


1. Update driver software




2. Browse my computer for driver software




3. Let me pick from a list of device drivers on my computer



4. Choose Ports(COM & LPT)



5. Choose LOCOSYS Technology Inc.




6. Choose Yes



7. Done



 Update Driver Software - LOCOSYS Technology GPS Receiver (COM4)

Windows has successfully updated your driver software

Windows has finished installing the driver software for this device:



LOCOSYS Technology GPS Receiver

Close