







ASSEMBLY INSTRUCTION


NC*FXX & NC*MXX | XLR Cable Connector


(A) 

(B) 

(C) 

(D) 

(E) 

(F) 

(A) Slide the boot onto the cable.

(B) Prepare cable as shown.

(C) Insert wires into the terminals and solder them.





(D) Put chuck onto the cable.
Attention: Pay attention to the guiding key.

(E) Slide insert and chuck together into the housing.





(F) Finish the installation by turning the bushing onto the connector.

ORDER OF ASSEMBLY

NC*FXX

			
bushing	chuck	insert	housing

NC*MXX

			
--	---	---	---

NEUTRIK AG NEUTRIK Zürich AG NEUTRIK USA Inc. NEUTRIK (UK) Ltd.	LI CH USA UK	T: +423 / 237 24 24 F: +423 / 232 53 93 T: +41 44 / 736 5010 F: +41 44 / 736 5011 T: +1 732 / 901 9488 F: +1 732 / 901 9608 T: +44 1983 / 811 441 F: +44 1983 / 811 439	NEUTRIK Vertriebs GmbH NEUTRIK France NEUTRIK Tokyo Ltd. NEUTRIK Hong Kong Ltd.	DE/NL/AT FR JP HK	T: +49 8131 / 280 890 F: +49 8131 / 280 830 T: +33 1 / 4131 6750 F: +33 1 / 4131 0511 T: +81 3 / 3663 4733 F: +81 3 / 3663 4796 T: +852 / 2687 6055 F: +852 / 2687 6052
---	-----------------------	--	---	----------------------------	--

Draft. Nr.: BDA 158 / 3102M1381 | Update: 12..03.2008 | Data subject to change without prior notice. ©2008NEUTRIK®. ALL RIGHTS RESERVED.