PSP141283PAQ

date/contact: 280416/CMA finishing: TKI last update: - drawing: 94021 unit: - / mm tolerance: -

1/4

EVE GmbH Hollefeldstr. 16 48282 Emsdetten Tel.: +49 (0) 25 72 / 93 51 - 0 Fax: +49 (0) 25 72 / 93 51 - 24 www.eve.de • info@eve.de






1. Electrical Characteristics

page:

Oscillation Frequency (KHz)	4.1 ± 0.5	
Operating Voltage (Vdc)	3 ~ 15	
Rated Voltage (Vdc)	12	
Current Consumption (mA/max.)	10 at Rated Voltage	
Sound Pressure Level (dB/min.)	83 at 10cm at Rated Voltage	
Tone/Pulse Rate	Constant	
Operating Temperature (°C)	-20 ~ +70	
Storage Temperature (°C)	-30 ~ +80	
Wave soldering conditions	245±5°C for 3±0.5 seconds.	
Manual soldering conditions	350±20°C / within 5sec	

2. Voltage/ Current / Sound Pressure



PSP141283PAQ

date/contact: 280416/CMA finishing: TKI last update: drawing: 94021

last update: - drawing: 94021 unit: - / mm tolerance: - page: 2/4

EVE GmbH Hollefeldstr. 16 48282 Emsdetten


Tel.: +49 (0) 2572/9351-0 Fax: +49 (0) 2572/9351-24 www.eve.de • info@eve.de





3. Dimensions and Material

3-1 Shape



Unit: mm

]

3-2 Material

Housing	ABS 777D UL94HB plastic resin (Color : Black)
Leading Pin	Tin Plated Brass
Weight (Gram)	0.8

date/contact: 280416/CMA finishing: TKI last update: -

last update: cdrawing: 94021 unit: -/mm tolerance: page: 3/4

EVE GmbH Hollefeldstr. 16 48282 Emsdetten

Tel.: +49 (0) 25 72 / 93 51 - 0 Fax: +49 (0) 25 72 / 93 51 - 24 www.eve.de • info@eve.de






4. TESTING METHOD

· Standard Measurement conditions


Temperature:25±2 ℃ Humidity:45-60%

· Acoustic Characteristics

The oscillation frequency, current consumption and sound pressure are measured by the measuring instruments shown below.



In the measuring test, buzzer is placed as follows:



PSP141283PAQ

date/contact: 280416/CMA finishing: TKI last update: - drawing: 94021 unit: - / mm tolerance: -

4/4

EVE GmbH Hollefeldstr. 16 48282 Emsdetten Tel.: +49 (0) 2572/9351-0 Fax: +49 (0) 2572/9351-24 www.eve.de • info@eve.de





5. RELIABILITY

page:

ITEMS	METHOD OF TEST AND MEASUREMENTS	PERFORMANCE
Coldness	After 98 hours of being exposed to -30 ${\mathcal C}$	No abnormality
withstanding	environment, should be returned to normal	shall exist
	environment for 2 hours, then re-proceed to test.	
Hotness	After 98 hours of being exposed to +80 ${\mathcal C}$	No abnormality
withstanding	environment, should be returned to normal	shall exist
	environment for 2 hours, then re-proceed to test.	
Humidity	After 98 hours of being exposed to 40 $^\circ\!$	No abnormality
withstanding	environment in actual operation, should be	shall exist
	returned to normal environment for 2 hours, then	
	re-proceed to test.	
Durability	Testing after 1,000 hours actual continuous	No abnormality
	operation.(at standard measurement conditions)	shall exist
Drop	A natural drop from 75cm high down to the	No abnormality
withstanding	ground.	shall exist
Vibration	Vibration of 2,000 cycles per minute, 2mm	No abnormality
withstanding	amplitude, applied in X, Y and Z directions for 30	shall exist
	minutes each.	

6. PACKAGE METHOD

- <1> One inner box consists of 1200pcs.
- <2> 10 inner boxes are packed in a carton box. (L*W*H=510*330*300mm) (12000pcs of PK-12N40PAQ are packed in a carton box.)

< 3 > RoHS Mark

