

514 330

75VA / 3A



4 - 7 = 230V

16 - 18 = 6V

12 - 18 = 24V

1 - 12 = 12V

1 - 16 = 30V

12 - 16 = 18V

1 - 18 = 36V

P S

(Z)

10

11

12 - 24V

7

(Z)

230V

4

(K)

16 - 6V

18 - 0V

20

36V - 1

(K)

