

























DE	Montageanleitung	WERKBANK
EN	ASSEMBLY INSTRUCTION	WORKBENCH
CZ	MONTÁŽNÍ NÁVOD	PONK



WT37

NO.	PHOTO	Q'TY	NO.	PHOTO	Q'TY
01		1	13		1
02		4	14		1
03		1	15	 1120X580X4.5mm	1
04		4	16	 420x395x6mm	4
05		4	17	 1128x610x16mm	1
06		2	18	 1123x605x16mm	1
07		8	19		4
08		4	20		4
09		4	21	 M6 x10 mm	84
10		2	22	 M6 x15mm	11
11		1	23		95
12		1	24		95

